

## WURLITZER SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"

ARE WELCOME AT ANY TIME

WURLITZER SERVICE DEP'T., NORTH TONAWANDA, N. 1

SUBJECT

Lubrication of Record Takeout Arm Bevel Gear.

EFFECTIVITY:

All Model 3400, 3410 and 3460 Phonographs manufactured and shipped between the approximate dates of November 21, 1969 and February 9, 1970.

PROCEDURE:

To lubricate the Record Takeout Arm Bevel Gear perform the following:

With the Record Changer in the "at rest" position, apply a light coating of Grease, Part Number 68684B, to the top of the Record Takeout Arm Bevel Gear between both Gear and Plate Assemblies

Cycle Record Changer with odd and even number selections a few times to insure application of grease on Gear and Plate Assemblies.

Phonographs manufactured and shipped after February 9, 1970 will have already been lubricated. This lubricant is Dow Corning Grease Compound 33 and may be purchased from the Wurlitzer Parts Department under Part Number 68684B (4 oz. jar).