

WURLITZER SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"

ARE WELCOME AT ANY TIME

WURLITZER SERVICE DEP'T., NORTH TONAWANDA, N. Y.

SUBJECT:

All 3500 Series Junction Boxes and all Model 268 and 269

Steppers.

COMPLAINT:

Relays located on the underside of these units not identified


for electrical identification.

CORRECTIVE ACTION:


This Service Slant is provided to properly identify the

unidentified relays as to schematic designation and electrical

function. See the following Figures:




JUNCTION BOX Figure 1.



268 STEPPER

Figure 2.



269 STEPPER Figure 3.