



# SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS" ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

November 8, 1947

To All Servicemen:

SUBJECT: PART NO. 45617 RELAY FOR MODEL 216 IMPULSE RECEIVER.

Part No. 45617 Relay has been obsoleted and is no longer available. Part No. 48833 Relay has been substituted in production, and will be shipped in place of the obsoleted item in all parts orders as Part No. 48833.

Part No. 48833 Relay is supplied mounted to a bracket. If used to replace a relay of the same type in a later Model 216 Receiver, the bracket is removed and the relay installed in the same manner as the original relay.

In early Model 216 Impulse Receivers, the method of installing Part No. 48833 Relay is illustrated below. NOTE THAT MOUNTING BRACKET IS SHOWN IN CORRECT POSITION.

