



WURLITZER SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"
ARE WELCOME AT ANY TIME

WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

SUBJECT. Revised Stylus Pressure Adjustment.

AFFECTING: 3400 Series Service Manual RECORD CHANGER ADJUSTMENT
Section C, Page 19C and STYLUS PRESSURE ADJUSTMENT
Paragraphs A through C.

REVISED ADJUSTMENT: With the record changer in play position and with the
tone arm resting on the record, adjust the weight in
the rear of the tone arm so that it requires 5 to 7
grams to lift the stylus from the record.

All Wurlamatic mechanisms manufactured on or after December 12, 1969 have been
adjusted to meet the above revision requirements.

3400 Series Phonographs already in the field and operating will not be im-
mediately affected by this Service Slant. However, if readjustment of
stylus pressure is ever required on machines manufactured either prior to or
after December 12, 1969, readjust according to the adjustment procedure of
this Service Slant.