

FO-604

MPU TESTER, TE-635-2, REVISIONS

To facilitate the testing of the new expanded memory MPU boards, AS-2518-35, some changes are required in the tester program and procedure. The changes are outlined below. (Memory parts are available from Bally Service department.)

PROM Changes:

Replace the following PROMs in the MPU tester, TE-635-2:

<u>Socket No.</u>	<u>New P/N</u>
U8	E-726-10
U7	E-726-02
U6	E-726-03
U5	E-726-04
U4	E-726-11
U3	E-726-21
U2	E-726-07
U1	E-726-22

A few testers exist that use 2708 PROMs instead of those used in the final model. These testers must have a PROM set installed per the following table.

<u>Socket No.</u>	<u>New P/N</u>
U7	E-726-13
U5	E-726-14
U3	E-726-19
U1	E-726-20

Attach a label to the front panel of the tester as follows:

"TE-635-2"
MODIFIED PER
FO-604

First Use: 1119-E

Date Issued: JUL 0 6 1978
Last Revision: