



# SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"  
ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

SUBJECT: Fuse replacement on the Stereo Power Supply Unit used in the  
2400 Series Phonographs

A change in fusing of the low voltage D. C. Circuit has been made. The three ampere regular fuse should be replaced with a two ampere Slo Blo Littelfuse. This results in better overall operation.

It is important that only the two ampere Slo Blo Littelfuse be used. Do not use any other make. Remember only the two ampere Slo Blo Littelfuse gives adequate protection to the silicon rectifiers.

Please caution all service personnel that the use of any other type, make or size of fuse may result in damage to the silicon diode rectifiers. In particular, do not use Bussman Fusetrons in this circuit. These are also the slow acting type but do not give the necessary protection.