

ESTABLISHED
1856

THE WURLITZER COMPANY

NORTH TONAWANDA, NEW YORK 14120

NORTH
TONAWANDA
DIVISION

February 26, 1973

TO ALL WURLITZER DISTRIBUTORS

Dear Distributor:

We have received a few isolated complaints from the field regarding a failure of Transistor TR-2 on the timing board which is used in the control box. To prevent future failures of this device we have added a series switch to the keyboard assembly along with a diode to protect the 3700, 3760 and 7500A Phonographs from future failures. The keyboard used on the Model 3710 only requires the addition of the series switch...no diode needed. We have also added a diode across TR-2 from emitter to collector to provide the ultimate in protection of this transistor which is used in all 3700 Series control boxes.

At the present time there are a few phonographs in the field with a recently added series switch. However, these will require the addition of two diodes on the Models 3700, 3760 and 7500A. The Model 3710 which were shipped with the new added series switch will require the addition of one diode.

We are sending under a separate mailing to your service department a service slant to provide the necessary technical information for installing the switch and diodes.

These parts will be shipped along with installation instructions to cover each machine you have purchased. All parts, such as diodes, switch mounting screws and switches, will be in a bulk shipment, all sent free of charge to the distributor.

We are thanking you in advance for your cooperation in the above subject.

Sincerely yours

THE WURLITZER COMPANY



C. B. Ross
Service Manager

CBR:AH