

TO ALL WURLITZER DISTRIBUTORS:

SUBJECT: Fuse Failure

The following may lead to a solution in cases of repeatedly blown fuses for which there seems to be no apparent cause:

Fuse Contact Surfaces Must Be Clean and Bright: the contact surfaces on the fuses and on the fuse clips must not be oxidized or dirty.

Fuse Contacts Must Be Tight: contact area without contact pressure is worthless. The fuse must be gripped tightly by the fuse clips. Contact of the fuse clip to the connecting plate and to the wire must be absolutely tight.

Any loose, corroded or oxidized contact will produce abnormal heating and cause the fuse to blow.

