



SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"
ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT. NORTH TONAWANDA, N. Y.

1250 GEAR BOX LUBRICANT

1217

Due to the number of requests from the field, we have investigated the possibility of using another type of lubricant, should the gear box need refilling.

Favorable results have been obtained here and on trial runs on locations using a Texaco Universal Gear Lubricant No. 90 E. P.

This would be available at Texaco Service Stations where it is usually carried in a large drum equipped with pump.

This lubricant may also be ordered from the Rudolph Wurlitzer Company where it is stocked in 5 lb. cans (about $\frac{1}{2}$ gallon) under Part No. 54070-A.

The gear box should be removed from phonograph, drained, thoroughly cleaned, and refilled to the over-flow plug. The major portion of the oil may be added while cover is off gear box and brought up to the proper level when reinstalled on the record changer. This lubricant is of the consistency that can be handled in ordinary oil can.