



# SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS" ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

SUBJECT: Model 255 Stepper  
Polarity of Electrolytic Condenser.

Should it ever become necessary to replace the 1000 Microfarad electrolytic condenser on the Model 255 Stepper, the "+" or positive lead must be connected to the ground lug as shown in figures 1 and 2.

