



SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"
ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

SUBJECT: Coin Paddle Modification

Model 5207 Wall Box and Model 1800 Coin Register

In cases where trouble is experienced with two plays for a nickel on Model 5207 and 1800 coin mechanisms, it may be found that the Coin Selector Lever interferes with the Coin Paddle. This condition may be corrected by modification of the Coin Paddle as follows:

1. The downward angle of the quarter section of the coin paddle was 15° as shown in Fig. 1. This angle has been increased to 25° as shown in Fig. 2.
2. Also a portion quarter section of the paddle is turned straight downward at a point $11/64$ " in from the turned edge marked (X) in Fig. 2.
3. This modification may be accomplished with a needle point pliers when the paddle is removed from its mounting bracket.
4. In cases where the coin mechanism is changed to nickel play the modification, as described above, should be accomplished in order to insure complete freedom of action of the Coin Selector Lever when it is lifted to engage the nickel Coin Counter Disc.

