



SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS" ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

SUBJECT: Selector Alignment Fixture, Models 1700 and 1800.

1. Alignment Fixture (Part No. 61672-6) has been developed to replace the original Alignment Sleeve (Part No. 61672-1) and is now available under the former part number.
2. Its use does not involve the removal of any parts but does provide a simple means for accurate alignment of the Electric Selector Assembly with the Selector Crank.
3. With the fixture attached to the selector crank as shown in the figure, the electric selector assembly should be adjusted laterally to provide equal clearance from the selector latch pins to the tip of the fixture in all positions of the selector crank.

