



SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"
ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

March 22, 1948

TO ALL WURLITZER DISTRIBUTORS

SUBJECT: Model 1100 Encore Program Selector Center Housing Assembly
And Torsion Spring

The center housing assembly as used in the Encore Program Selector has been made available as a service part. This item was previously not available as a separate assembly and is not shown as such in the Model 1100 Parts Catalog. Please order as Part Number 52379, Model 1100, Center Housing Assembly.

This part will include all gears, program change key levers assembly, main drive shaft (spring motor) and electric motor micro switch, but does not include electric motor assembly or rear cover plate. This item is shipped assembled as shown below.

Torsion spring Part No. 49081 has also been made available as a service part. This is the spring which is used in the main cam gear and escapement disc assembly in the encore program selector (not shown in 1100 Parts Catalog).

